

Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

ENGINEERING CHANGE REQUEST

Tel (613) 632-5200 Fax 613 632-5246

			. 47	613 632-52	-	ECR	2 58					
Data Open	٠d٠		9/21/20 12:04 F	ON A				I Dv:	Auglair (Guillauma		
			Drawing/Patteri				Requested By: Responsible Engineer:		Auclair, Guillaume Fuentes, Roberto			
Priority:			Low	ii Orlange			Requester	_		Guillaume		
Status:			Under Review				DE Approv		Provence			
				nge 3 C2 and 5-C	•••		Drouin, Steven					
110000111			Missing RAD on drawing page 3 C2 and 5-C2 see attached documentation				ECR Lead*:		Drouin, Steven			
Expense: 300					DM:	•	Seib, Victoria					
Target Date:									00.0, 1.0			
Execution I	Date:											
ECR Appro	val No) :										
RE (R&D): Status Note:							**BRIEF DESCRIPTION**:		D5638 /D5639 Saddle Outbo			
Status NOTE	·.						DESCRIPTION/ ADR CONTENT**:		CNC department came to see engineering with a issue Missing RAD on drawing page 3 C2 and 5-C2 see attached documentation, Ref D3883, D3884 Saddle and D2933 Saddles at the same area have a Rad of 0.025 and a chamfer of 0.025			
									Deviation Saddle d	n allowed rawing re 0.025" an	Conclusion	id a chamfer of 0.025 n: D5638/D5639 ections B-B & E-E: .025"x45degree
					CUSTO	MER A	APPROV	ALS				
Customer Customer Visible					Cus	Customer Approval Required				* Customer Approved		
					ΔΤΤΔΟ	НМЕ	NT PAGE	-S				
			Г	Document N		·····				Do	cument No	ote
SHBY-PRT-EN20092111060.pd												
			0.15.1	111 2112000	z m rood.pai	PAR	PTS PT					
Part No R	ev Part Status Name Type		Туре				I Commer	Comments Documents				
D5638-1	_	On hold			Sub-assembly	Guste	omer rare	Орсон	i comments			500aments
D5638-2		On hold		Saddle, Outboard, RH								
D5639-1		On hold		board, LH	Sub-assembly Sub-assembly							
D5639-1		On hold		· · · · · · · · · · · · · · · · · · ·	Sub-assembly							
D3039-2		On noic	Jaudie, III	board, IXII	INVENTO	DRY D	DISPOSIT	TION				
Part No I	Revisi	on	Material No	Current	Inventory Qty			ng On-Order (Otv	Otv S	cheduled	for Production
D5638-1			6 *				0 *		J	0 Adjust Jobs Scheduled		
D5638-2			6 *				0 *			0 Adjust Jobs Scheduled		
D5639-1			6 *				0 *			0 Adjust Jobs Scheduled		
D5639-2			6 *				0 *			0 Adjust Jobs Scheduled		
D30.	JU-Z			U	۸۵۵۵	`	ING JOB	9		<u> </u>	1,431 0003	Concadica
					ACCC	JUNII		<u>.</u>		-		Otatus
		مردد	ting Joh No			Sustain Engineering						
	A		ting Job No AD 1057			Cur	Type	poring		Gr	oup	Status Active

Effect Group	Effects					
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (D5638 D5639), Update/Create MDL (Update per lasted revisions)					
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review (Deviation allowed)					
4. Production Type	In-house production (D5638 D5639)					
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors (D5638 D5639)					
6A. Production Impact	Update/Create CNC Program (D5638 D5639)					
9. Sustaining Cost Grouping	Poor Quality					